

## Fusion720 Inline wrapper Diagnostic procedure



### - Bale kicker sensor (O)

The sensor (O) allow the Fusion720 to detect when the bale kicker mechanism is fully retracted.

The flat head surface of the sensor shall be about  $\frac{1}{4}$  inch away from the mechanism

