


## FAUTE #2 COMMUNICATION IOX024

Communication inexistante entre le contrôleur MC050 et le IOX24

1 – Valider que les témoins lumineux du IOX024 clignote. S’il clignote, alimentation électrique est OK donc inspecter fil jaune et vert Canbus à partir de l’écran jusqu’au IOX024

2 – Si les témoins lumineux n’allume pas, inspecter le fil noir et rouge entre l’écran et connecteur 12pin gris du IOX024.




# DIAGRAMME ÉLECTRIQUE

Pour plus de détail consulter le diagramme électrique de la machine:

- 1- Rendez-vous au [www.grpanderson.com](http://www.grpanderson.com)
- 2- Cliquer sur Documentation
- 3- Sélectionner le dossier – Electric Wiring Diagram –
- 4- Sélectionner le dossier associé à votre machine – Stackpro5400 ou Stackpro 7200 –

Ou suivez le lien ci-dessous:

<https://grpanderson.com/en/resource-center/?section=2-Public%20section/-%20Electric%20wiring%20diagram%20->



The screenshot shows the Anderson website's resource center. A red line with numbers 1 through 4 indicates the navigation path:

- 1: The website URL [www.grpanderson.com](http://www.grpanderson.com) in the browser address bar.
- 2: The "Resource center" link in the top navigation menu.
- 3: The "ELECTRIC WIRING DIAGRAM" folder in the "FORMS" section.
- 4: The "STACKPRO5400" and "STACKPRO7200V2.0" folders in the list below.

**TROUVER UN  
CONCESSIONNAIRE**

**SECTION  
DOCUMENTATION**

**ACCÉDER À L'ESPACE  
CONCESSIONNAIRE**