


Second arm lock valve kit on a 780SB

If the 2nd stretcher folding arm goes down when out of service, the installation of that kit will solve the problem.

The part # is 224234-1.



Second arm lock valve kit on a 780SB

Installation on the cylinder.



Second arm lock valve kit on a 780SB

Here is the installation of the lock valve.

