PROCEDURE REF A-IND-034




Charging system verification

If the battery does not hold the charge even if the Honda engine is running, there are two technical possibilities:

- First of all, the emergency stop/start button has maybe turn on itself. If the button is misaligned, the plastic corners (#3 - #4 - #5 - #6) will push the contact connectors (#1 - #2) that will stop the battery charging.





PROCEDURE REF A-IND-034



Charging system verification

- Secondly, there are 2 wires connected to the Honda engine that could be bad attached (photo #2). It is important that the grey and the white wires are well plugged because they are linked through the Honda charging regulator.

